



# Magnicator® Model Code



## OPTIONS

- AS = Acrylic Scale
- MS = Metric Scale (cm/m)
- PS = Percentage Scale
- NGS = Negative Scale
- SS = Special Scale (Specify Type)
- SP = Set Point Arrows (Specify QTY)
- DI = Dual Indicator
- IF = Interface
- FP = FlashProof™
- NF = Non-Frost Extension
- EH = Electric Heat Trace
- CI = Cold Insulation (NF Required)
- ST = Steam Traced
- IB = Insulation Blanket
- BW = All Butt-Weld Construction
- WN = Weld Neck Flanges
- RJ = Ring Joint Flanges
- SE = Stub End/Lap Joint Flanges
- VV = Valves (Specify)
- FF = Smooth Finish Flanges
- SW = Socket Weld Process Flanges
- NS = No Scale
- NI = No Indicator
- DV = 3/4" Vent/Drain, Plugged
- X = Other (Specify)



Contact factory for MC style gages.